

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending
Active
L1: (111) (296/220.01).CCLS.
L2: (217) (296/107.08).CCLS.
L3: (63) (296/136.06).CCLS.
L4: (47) (296/107.2).CCLS.
L5: (103) (296/147).CCLS.
L6: (116) (296/146.16).CCLS.
L7: (91) (296/146.14).CCLS.
L8: (131) (296/107.07).CCLS.

Failed
Saved
(5) ("5545361") or ("5799991") or ("5988713") or (
(7) ("5092512") or ("5124186") or ("5139297") or (
(6) ("4165113") or ("4221413") or ("4320913") or (
(5) ("5,092,512") or ("6,406,081") or ("5,799,991"
(1148) ((293/15) or (293/102) or (293/120-121) or (
(5) ("4,615,411") or ("4,347,277") or ("3,885,521"
(4) ("4592886") or ("6592069") or ("4329879") or (
(1) ("3934064").PN.
(1) ("20008201").PN.
(1) ("2789043").PN.
(1) ("4615411").PN.
(3) ((("10005718") or ("29916470"))).PN.

Search List Browse Queue Clear
DBs USPAT; US-PGPUB
Highlight all hit terms initially

296/107.07

U	I	Document ID	Issue Dat	Page	Title	Current
44	<input type="checkbox"/>	US 2054783	19360915	6	Car construction [TEXT AVAILABLE IN USOCR DATA A	105/409
45	<input type="checkbox"/>	US 2040307	19360512	7	Car wall construction [TEXT AVAILABLE IN USOC A	105/409
46	<input type="checkbox"/>	US 2010381	19350806	4	Railway car side wall [TEXT AVAILABLE IN USOC A	105/409
47	<input type="checkbox"/>	US 20020014782	20020207	23	Retractable top tonneau cover_assembly_and_modu	296/107
48	<input type="checkbox"/>	US 20010004156	20010621	5	Tonneau cover system	296/76
49	<input type="checkbox"/>	US 6663163	20031216	10	Cover device for a folding_top_compartm	296/107
50	<input type="checkbox"/>	US 6582009	20030624	6	Convertible vehicle with_a_wind_deflector	296/180
51	<input type="checkbox"/>	US 6293605	20010925	23	Retractable top tonneau cover_assembly_and_modu B1	296/76
52	<input type="checkbox"/>	US 6254165	20010703	11	Tonneau cover and decklid_linkage_and_dri B1	296/76
53	<input type="checkbox"/>	US 5944378	19990831	11	Two-part convertible top_for_a_motor_vehicle A	296/219
54	<input type="checkbox"/>	US 2845299	19580729	5	Vehicle top compartment cover_mechanism [TEXT A	296/136
55	<input type="checkbox"/>	US 20020067054	20020606	29	Automotive vehicle open air_system	296/216
56	<input type="checkbox"/>	US 4852935	19890801	9	Retractable backlight A	296/146

His Details HTML

Ready

EAST - [lined duct:2]

File View Edit Tools Window Help



- Pending
- Active
 - L1: (111) (296/220.01).CCLS.
 - L2: (217) (296/107.08).CCLS.
 - L3: (63) (296/136.06).CCLS.
 - L4: (47) (296/107.2).CCLS.
 - L5: (103) (296/147).CCLS.
 - L6: (116) (296/146.16).CCLS.
 - L7: (91) (296/146.14).CCLS.
 - L8: (131) (296/107.07).CCLS.
- Failed
- Saved

- (5) (("5545361") or ("5799991") or ("5988713") or (
- (7) (("5092512") or ("5124186") or ("5139297") or (
- (6) (("4165113") or ("4221413") or ("4320913") or (
- (5) (("5,092,512") or ("6,406,081") or ("5,799,991"
- (1148) ((293/15) or (293/102) or (293/120-121) or (
- (5) (("4,615,411") or ("4,347,277") or ("3,885,521"
- (4) (("4592886") or ("6592069") or ("4329879") or (
- (1) ("3934064").PN.
- (1) ("20008201").PN.
- (1) ("2789043").PN.
- (1) ("4615411").PN.
- (3) (("10005718") or ("29916470")).PN.

Search List

DBs: USPAT:US-PGPUB Highlight all hit terms initially

296/107.07

... (The right pane shows a large, mostly blank search result area)

- Drafts
- Pending
- Active
- Failed
- Saved
- Favorites
- Tagged (56)
- UDC
- Queue
- Trash

Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
IS&R	L1	111	(296/220.01).CCLS.	USPA T; U	2004/11/0 3 06:52		
IS&R	L2	217	(296/107.08).CCLS.	USPA T; U	2004/11/0 3 07:06		
IS&R	L3	63	(296/136.06).CCLS.	USPA T; U	2004/11/0 3 07:10		
IS&R	L4	47	(296/107.2).CCLS.	USPA T; U	2004/11/0 3 07:13		
IS&R	L5	103	(296/147).CCLS.	USPA T; U	2004/11/0 3 07:15		
IS&R	L6	116	(296/146.16).CCLS.	USPA T; U	2004/11/0 3 07:18		
IS&R	L7	91	(296/146.14).CCLS.	USPA T; U	2004/11/0 3 07:20		
IS&R	L8	131	(296/107.07).CCLS.	USPA T; U	2004/11/0 3 07:21		

Details

HTML

Ready

NUM